

2/16/87 MUST BE FILLED  
OUT COMPLETELY

Inspector's Name Schoellkopf  
Date of Documentation 11/20/86

SPCC COMPUTER SCREEN

Amendment? Y N

Facility Name Lancia Oil Company

Address 340 So River Road

City Hickensack

County Bergen

State NJ

Zip Code 07601

Telephone (201) 342-5454

Is Facility Regulated Under 40 CFR 112? Yes

Field Inspection/Desk Review/308 Reply/Other (Circle One)

Inspectors W.E. Schoellkopf

Navigable Water Affected

\*Status of SPCC Plan

Storage Capacity (total gallons) 1215,000

Above ground capacity (total gallons) 1,215,000

Below ground capacity (total gallons) -0-

†Date of Field Inspection 11/19/86

†Date of Desk Review(at office, not Field)

†Date of Reinspection or Review

†Date Implementation Schedule Due

†Date 308 SPCC Letter Reply was received

†Date Notice of Violation was issued

†Date of Oil Spill (if applicable)

Amount of Oil Spilled

†Plan To Be Fully Implemented on

†Reissue of Non-Compliance Letter

†Date Notice of Compliance was issued

Comments (10 Characters)

235240



# SPCC REPORT CHECKLIST

FACILITY: Lanora Oil Company LOCATION 340 S. River St  
 EPA PM: Doug Kodama TAT PM: Hackensack NJ  
Manfreda  
 DOCKET/CASE # \_\_\_\_\_ TDD # 2-8611-42

FORM/LETTER		INCLUDED	NOT INCLUDED
SPCC Computer Screen (Original)		✓	
PCB Screening Form (Original)			
EPA Letter to Facility (Certified Mail) with Attachments		✓	
EPA Letter to Local Representative with Attachments		✓	
EPA File Copy (Yellow cc) with Originals of Attachments		✓	
Required cc and bcc Copies		✓	
EPA Project Manager's Copy		✓	
Additional White Copies of Memo/Letters for EPA PM		✓	
Attachments:	TAT Letter Report	✓	
	A - SPCC Inspection Field Sheet	✓	
	B - SPCC Inspection Field Sheet		
	C - Detailed SPCC Documentation		
Other (Specify): <u>Field Drawing</u>		✓	
<u>Photographs</u>		✓	

DISCUSSION: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_